



The World Leader in Vibrating Wire Technology

*48 Spencer Street
Lebanon, NH 03766, USA
Tel: 603•448•1562
Fax: 603•448•3216
E-mail: geokon@geokon.com
<http://www.geokon.com>*

Instruction Manual

Model 1610

The Geokon/Ealey
Tape Extensometer

No part of this instruction manual may be reproduced, by any means, without the written consent of Geokon, Inc.

The information contained herein is believed to be accurate and reliable. However, Geokon, Inc. assumes no responsibility for errors, omissions or misinterpretation. The information herein is subject to change without notification.

Copyright © 2002, 2004, 2008, 2009 by Geokon, Inc.

(Doc Rev E, 12/09)

Warranty Statement

Geokon, Inc. warrants its products to be free of defects in materials and workmanship, under normal use and service for a period of 13 months from date of purchase. If the unit should malfunction, it must be returned to the factory for evaluation, freight prepaid. Upon examination by Geokon, if the unit is found to be defective, it will be repaired or replaced at no charge. However, the WARRANTY is VOID if the unit shows evidence of having been tampered with or shows evidence of being damaged as a result of excessive corrosion or current, heat, moisture or vibration, improper specification, misapplication, misuse or other operating conditions outside of Geokon's control. Components which wear or which are damaged by misuse are not warranted. This includes fuses and batteries.

Geokon manufactures scientific instruments whose misuse is potentially dangerous. The instruments are intended to be installed and used only by qualified personnel. There are no warranties except as stated herein. There are no other warranties, expressed or implied, including but not limited to the implied warranties of merchantability and of fitness for a particular purpose. Geokon, Inc. is not responsible for any damages or losses caused to other equipment, whether direct, indirect, incidental, special or consequential which the purchaser may experience as a result of the installation or use of the product. The buyer's sole remedy for any breach of this agreement by Geokon, Inc. or any breach of any warranty by Geokon, Inc. shall not exceed the purchase price paid by the purchaser to Geokon, Inc. for the unit or units, or equipment directly affected by such breach. Under no circumstances will Geokon reimburse the claimant for loss incurred in removing and/or reinstalling equipment.

Every precaution for accuracy has been taken in the preparation of manuals and/or software, however, Geokon, Inc. neither assumes responsibility for any omissions or errors that may appear nor assumes liability for any damages or losses that result from the use of the products in accordance with the information contained in the manual or software.

TABLE OF CONTENTS

1. INTRODUCTION	1
1.1. THEORY OF OPERATION	1
1.2. CONSTRUCTION DETAILS	2
2. INSTALLATION.....	2
2.1. GROUTABLE ANCHORS	2
2.2. EXPANDING WEDGE ANCHORS	2
2.3. WELDABLE ANCHORS.....	3
3. TAKING READINGS.....	4
3.1 PRELIMINARY.....	4
3.2 TENSIONING THE TAPE.....	4
3.3 TAKING THE READING.....	5
4. TEMPERATURE CORRECTIONS.....	6
4.1. METRIC TEMPERATURE CORRECTION EXAMPLE	7
4.2. ENGLISH TEMPERATURE CORRECTION EXAMPLE	7
5. ZERO STABILITY CONTROL	8
6. MAINTENANCE.....	8
6.1 CARE OF THE TAPE – CHANGING TAPES.....	8
6.2 CARE OF THE INSTRUMENT	9
6.3 CARE OF THE BATTERIES	9
6.3.1 <i>The 9 volt Battery</i>	9
6.3.2 <i>The Digital Gage Battery</i>	9
7. SERVICING	9
8. SPECIFICATIONS	10

LIST of FIGURES, TABLES and EQUATIONS

FIGURE 1 - TYPICAL INSTALLATION	1
FIGURE 2 - MODEL 1610 TAPE EXTENSOMETER	2
FIGURE 3 - THREE ANCHOR TYPES	3
FIGURE 4 - TENSIONING THE TAPE.....	5
TABLE A-1 MODEL 1610 SPECIFICATIONS.....	10

1. INTRODUCTION

1.1. Theory of Operation

The Model 1610 Tape Extensometer is designed to measure changes in the distance separating two fixed points. Most often the points are located on opposite sides of an underground opening, such as a tunnel, and the measurement is usually of closure of the tunnel walls, (see Figure 1), or roof/floor convergence caused by pressure in the surrounding ground. The tape extensometer is particularly useful for the measurement of deformation of the shotcrete tunnel linings used as part of the "New Austrian Tunneling Method" (NATM). It also finds use in the measurement of closure between the walls of open cuts, in cut and cover operations and between the walls of deep foundation excavation. Other applications include structures, buildings and unstable slopes. By using the same fixed points to locate a leveling staff or EDM target, it is possible to incorporate tape extensometer data into a more comprehensive monitoring survey.




Figure 1 - Typical Installation

The Tape Extensometer has two purposes: to apply a consistent tension to a measuring tape, which has punched holes at regular intervals, and to provide an accurate reading of the distance from the punched hole being used to the eyebolt being measured.

1.2. Construction Details

Figure 2 shows details of the construction of the tape extensometer. The device consists essentially of a stainless steel measuring tape in which holes have been punched at regular intervals. This tape can be stretched between two points located on opposite sides of the underground opening. There is a hook on the end of the tape and another on the back end of the tape extensometer. A locating pin attached to sliding bars is designed to engage one of the punched holes in the tape. The correct hole is that which permits the tape to be tensioned to its correct tension as indicated by system of colored indicator lights. The tape extensometer can be shortened and the tape tensioned, by rotating a winding handle until a correct-tension indicator light is illuminated. At this moment the digital indicator will give the correct reading.

The precision of the instrument will depend to a large degree on the skill of the operator in achieving a consistent and repeatable tape tension. Techniques are described later, (see Section 3.2), which will maximize the precision and accuracy.




Figure 2 - Model 1610 Tape Extensometer

2. INSTALLATION

Anchor points are of three types as shown in Figure 3.

2.1. Groutable Anchors

An eyebolt is threaded into the end of a piece of $\frac{3}{4}$ " (#6) rebar and the rebar is grouted inside a short (9" or 250 mm) borehole, or cast inside the shotcrete lining (NATM).

2.2. Expanding Wedge Anchors

An alternative to grouting is to use a rockbolt type expansion shell anchor inside a 1 $\frac{3}{8}$ " diameter (35 mm) borehole. These anchors are recoverable.

2.3. Weldable Anchors

Occasionally anchors may be located on steel ground supports such as tunnel arches, steel tubing or on soldier piles. The eyebolt is attached to a small steel plate, which is then welded to the structure. (Alternately an eyebolt can be screwed directly into a ¼-20 hole drilled and tapped in the steel member.)




Figure 3 - Three Anchor Types

3. TAKING READINGS

3.1 Preliminary

Always make a careful note of the instrument and tape Serial Numbers when beginning a set of readings. Also note the temperature. Do not assume that the temperature underground will remain constant.

There is no on/off switch for the tension indicator lights - the tension device operates automatically. Ensure that the battery-holder contains a charged 9-volt battery before commencing and that the digital gage is on. If the gage is off, **switch it on simply by moving the tape tensioning winding handle** or by depressing the on/off button located on the face plate below the display panel.

To change the display units to either millimeters or inches remove the top cover plate and use the units selection button on the digital gage.

Before commencing, make sure that the display reads 0.00mm, (0.000inches), when the winding handle is turned fully clockwise until it will turn no more - it will come to a natural stop. DO NOT FORCE THE WINDING HANDLE. If the reading on the digital gage does not show 0.00mm, or 0.000inches, depress the zero button located next to the on/off button. Periodically check the zero reading from time to time, especially at the start of each set of measurements.

Turn the winding handle anti-clockwise until the sliding bars are fully extended, the gage should read at least 55mm, (2.200 inches).

(See Section 5 for recommended zero stability checking procedures)

3.2 Tensioning the Tape

Correctly tensioning the tape requires a certain amount of skill. It is recommended that the operator practice the recommended technique until it can be performed rapidly and consistently. Refer to Section 5 for further details.

3.2.1 Hook the tape onto the first eyebolt and the instrument onto the second eyebolt.

3.2.2 Using the tape reel handle, reel in the tape so as to remove as much sag as possible then place the nearest punched hole over the locating pin and secure in place by sliding the slotted clip all the way over the tape and pin.

3.2.3 Turn the tape tensioning winding handle clock-wise until one or both of the indicator-lights comes on. Turn the winding handle back a small amount until both lights go off.

3.2.4 Turn the winding handle clock-wise, in small increments, until only the green light is on when the instrument is at rest, untouched by the operator.

3.2.5 Place a finger under the tape, as shown in figure 4, and **gently** lift the tape so as to relieve a small amount of tension on the tape – the green light should go off. **Gently** removing the finger should cause the green light to come on again. If the green light stays off, turn the winding handle clock-wise a small amount until enough tension is being applied so that the green light goes on and off again with gentle placing and removing of the finger under the tape. The tape is now at the correct tension.




Figure 4 - Tensioning the Tape.

3.2.6 If the red light comes on the tape is over-tensioned, so turn the winding handle anti-clockwise and return to step 3.2.3. Alternatively, it may be that the finger-pressure being applied to the tape is too great, or, being applied too roughly.

3.2.7 The red light is set to illuminate at between 0.2 to 0.3 mm after the green light. Over long distances (15 meters or more), tape flutter may cause the red light to come on too soon. If this is the case, return the instrument to the supplier for adjustment, specifying the conditions under which the instrument is required to operate.

3.3 Taking the Reading

Once satisfied that the correct tape tension has been applied, take the reading on the digital gage. It may be necessary to twist the instrument in order to read the gage and this may cause the red or the green light to come on. However, the reading on the digital gage will remain the same so long as the winding handle is not moved.

The travel of the digital gage is slightly larger than the pitch of the punched holes. As a result it may be possible to take readings on two adjacent punched holes. Thus it might happen that continued movements carry the readings beyond the range of the slide bars, before that happens take readings on both tape holes that are within range of the slide bars. For example, if the reading increases to a reading higher than 52 mm switch to the next tape hole and take a second reading of around 1mm, (or vice versa if the

reading decreases to below 1mm), then continue to use this new tape hole in subsequent readings.

The total distance between the eyebolts is the sum of the distance along the tape indicated by the punched hole used, plus the digital gage reading, plus any correction that is required to account for temperature variations, as described in section 4. (Note that the first hole in the tape starts at the same dimension as the nominal length of the instrument from the centerline of the pin to the centerline of the hook on the back of the tape extensometer. In the case of metric units this is 500mm and, for the English units, 20 inches.)

After the reading has been taken, turn the winding handle clockwise, until the sliding bars are fully retracted, then remove the locating pin from the tape. The instrument is now ready for the next reading. For better accuracy it is recommended that all readings be repeated a number of times and the average taken.

4. TEMPERATURE CORRECTIONS.

The coefficient of thermal expansion, K, for the punched tapes is:

$$K = 11.6 \times 10^{-6} \text{ meters/meter/}^{\circ}\text{C}$$

or

$$K = 6.45 \times 10^{-6} \text{ meters/meter/}^{\circ}\text{F}$$

(Inches/inch can be substituted for meters/meter)

For a tape of length L and a temperature change ΔT , the apparent change of length of the tape ΔL due to ΔT is:

$$\Delta L = L K \Delta T$$

If the initial temperature is T_0 and a subsequent temperature is T_1 then let $\Delta T = (T_1 - T_0)$ and the apparent change in length is:

$$\Delta L = L K (T_1 - T_0)$$

For rising temperatures $T_1 > T_0$ the tape will expand, ΔL will be positive causing a subsequent reading R_1 at T_1 to be too small. Hence when $T_1 > T_0$ the correction to R_1 will be positive and when $T_1 < T_0$ the correction will be negative, or, correction to R_1 is:

$$L K (T_1 - T_0)$$

If we let $L = R_0$ expressed in the appropriate units then the required correction to R_1 is:

$$+ R_0 K (T_1 - T_0)$$

So if the apparent change in distance ΔD as measured by the difference between an initial reading R_0 at a temperature T_0 and a subsequent reading R_1 at a temperature T_1 then:

$$\Delta D_{\text{apparent}} = R_1 - R_0$$

and the true displacement ΔD_{true} corrected for temperature will be:

$$\Delta D_{\text{true}} = R_1 - R_0 + R_0 K (T_1 - T_0)$$

4.1. Metric Temperature Correction Example

A Metric type extensometer shows an initial reading (R_0) at 20°C (T_0) such that the tape pin falls in the hole located at 10.45 meters while the reading on the digital gage is 32.34mm or 0.03234 meters. The measurement is:

$$\begin{array}{r} 10.45 \\ + 0.03234 \\ \hline 10.48234 \\ \text{meters} \end{array}$$

A subsequent reading (R_1) taken at a temperature of 0°C (T_1) appears to be 10.49654 meters so the apparent displacement, $R_1 - R_0 = 0.01420$ meters or = + 14.20 mm.

The required correction for temperature is:

$$\begin{aligned} &+ (10.48 \times 1000) \times 11.6 \times 10^{-6} \times (0 - 20) \text{ mm} \\ &= -2.43 \text{ mm} \end{aligned}$$

So the true displacement is: $\Delta D_{\text{true}} = + 14.20 - 2.43$

$$= + 11.77 \text{ mm}$$

4.2. English Temperature Correction Example

An English type tape extensometer shows an initial reading (R_0) at a temperature of 30°F (T_0), such that the tape pin falls in a hole located at 34', 4" while the reading on the digital gage reads 1.378 inches.

The measurement is:

$$\begin{array}{r} 34' \ 4.00" \\ + \ 1.378" \\ \hline 34' \ 5.378" \end{array}$$

A subsequent reading (R_1) taken at a temperature of 80°F (T_1) appears to be 34', 6.262" equal to an apparent displacement $\Delta D_{app} = R_1 - R_0 = +0.884$ inches.

The required correction for temperature is:

$$+ (34.45 \times 12) \times 6.45 \times 10^{-6} \times (80 - 30) \text{ inches} \\ = + 0.133 \text{ inches}$$

And the true displacement is: $\Delta D_{true} = + 0.884 + 0.133$ inches
 $= + 1.017$ inches

5. ZERO STABILITY CONTROL

Always set up two test-point eyebolts mounted on a stable structure whose dimensions do not change. This can be between two walls of a stable underground opening or between opposite sides of a steel framework kept in a stable temperature environment. Use these test points at regular time intervals, preferably at the start of each measurement survey, to ensure that the self-length of the tape extensometer does not change with time. It is important that zero readings be accurate so repeat the reading a number of times, (5 or more), until the accuracy of the recorded value is beyond doubt.

The zero stability control points will also be useful for practicing the measurement technique described in Section 3.2.

Note: It is important that the test point eyebolts be stable, that is, firmly fixed and immovable. Eyebolts attached to objects, which can move even slightly will make it impossible to perform the measurement technique as described in Section 3.2.

It is good practice to extend the monitoring survey to a point outside the area likely to be affected by movements. In this way there will be seen to be confirmation that the tape extensometer records no movement in those areas where no movement is expected. This will go a long way to improving confidence in the readings taken from the active area.

Any gradual or sudden change in the zero reading will indicate the need for servicing and recalibrating the instrument. (See Section 7).

6. MAINTENANCE

6.1 Care of the Tape – changing tapes.

Care should be taken to keep the instrument clean. **Avoid dragging the tape along the ground at all times!** The tape should be treated with the same care as any precision surveying tape. **The greatest danger is kinking the tape** and extreme care should be taken to prevent traffic from damaging the tape while in use. When reeling in the tape pass it through a rag to remove dirt and moisture. Broken tapes can be replaced easily with new tapes. To remove an old tape simply grip the old tape and turn the tape handle in the opposite way to the reeling-in direction, Keep turning and the tape reel spindle will come

loose and can be pulled out of the tape reel. Then the new tape can be positioned over the tape reel with the looped inner end of the tape held in the notch. Then the reel is positioned back into the tape extensometer and the tape reel spindle pushed through the reel and threaded back into place in the tape extensometer body. There have been instances where moving traffic has blundered into the tape while readings are being taken resulting in a torn tape. A couple of bright orange post-it notes at mid span might go some way to prevent this happening.

6.2 Care of the Instrument

The instruments working life will be extended if care is taken to keep the instrument clean. Whenever the instrument has been exposed to dirt or moisture clean it with a soft cloth at the end of the day, paying particular attention to the sliding bars.

Store the instrument with the sliding bars retracted so that the gage reads between 3mm and 5mm.

6.3 Care of the Batteries

6.3.1 The 9 volt Battery.

The 9-volt battery powers the indicator lights. It can be removed if the instrument is to be stored for any length of time. The 9-volt battery holder is located on the rear face of the casing. The 9 volt battery should be replaced at least once every year or sooner if the indicator lights start to fade. **Failure to replace the battery after it has gone flat will prevent the tape tension lights from coming on which may lead to tape damage if the tape is over-tensioned.**

6.3.2 The Digital Gage Battery

A coin type battery, Model LR44, powers the digital gage. In order to preserve the life of the battery it automatically switches itself off after about 5 minute of idleness. Note that if the battery switches itself off between readings the zero setting will **not** be lost when the battery switches itself back on. A low battery indication is given when the display begins to flash on and off. To change the battery it is necessary to remove the face plate and remove 5 capscrews that hold the digital indicator in place,

Note that removing the battery will cause the gage to automatically reset to millimeters. If this happens with an English unit, depress the button on the digital gage to switch to English units. Re-attach the indicator and replace the cover.

7. SERVICING

It is recommended that the instrument be returned to the supplier at least once per year, for service and calibration. The instrument may be returned for a calibration check and the issue of a new calibration certificate at any time.

8. SPECIFICATIONS

Model 1610 Tape Extensometer Specifications

Available Ranges¹:	15m, 20m, 30m, (50 ft., 66ft, 100 ft).
Accuracy²:	±0.1mm, (±0.004in).
Repeatability³:	±0.1mm, (±0.004in).
Tension on the Tape	10 , kgf (22 lbs)
Overall Length	520mm. (20.5 inches).
Case Dimensions	500 × 350 × 125mm, (20 × 14 × 5in).
Weight (with case):	2 kg., (4.4 lbs).
Indicator and Digital	9volt
Gage Battery	Coin Type LR44

Table A-1 Model 1610 Specifications

Notes:

¹ Other ranges available.

² System accuracy. Accuracy of the digital gage equal to the resolution (±1 graduation) = 0.01mm

³ Repeatability – this is the system accuracy to be expected under normal conditions and takes into account trained operator error, friction in the system, temperature variations and placement errors. The repeatability is affected by the environmental conditions under which the readings are taken and may be significantly worse than as shown.