



The World Leader in Vibrating Wire Technology

*48 Spencer Street
Lebanon, NH 03766, USA
Tel: 603•448•1562
Fax: 603•448•3216
E-mail: geokon@geokon.com
<http://www.geokon.com>*

Instruction Manual

Model 4500MLP

Multi-level Vibrating Wire Piezometer



No part of this instruction manual may be reproduced, by any means, without the written consent of Geokon, Inc.

The information contained herein is believed to be accurate and reliable. However, Geokon, Inc. assumes no responsibility for errors, omissions or misinterpretation. The information herein is subject to change without notification.

Copyright © 2003, 2004, by Geokon, Inc.

(REV C, 04/07)

Warranty Statement

Geokon, Inc. warrants its products to be free of defects in materials and workmanship, under normal use and service for a period of 13 months from date of purchase. If the unit should malfunction, it must be returned to the factory for evaluation, freight prepaid. Upon examination by Geokon, if the unit is found to be defective, it will be repaired or replaced at no charge. However, the WARRANTY is VOID if the unit shows evidence of having been tampered with or shows evidence of being damaged as a result of excessive corrosion or current, heat, moisture or vibration, improper specification, misapplication, misuse or other operating conditions outside of Geokon's control. Components which wear or which are damaged by misuse are not warranted. This includes fuses and batteries.

Geokon manufactures scientific instruments whose misuse is potentially dangerous. The instruments are intended to be installed and used only by qualified personnel. There are no warranties except as stated herein. There are no other warranties, expressed or implied, including but not limited to the implied warranties of merchantability and of fitness for a particular purpose. Geokon, Inc. is not responsible for any damages or losses caused to other equipment, whether direct, indirect, incidental, special or consequential which the purchaser may experience as a result of the installation or use of the product. The buyer's sole remedy for any breach of this agreement by Geokon, Inc. or any breach of any warranty by Geokon, Inc. shall not exceed the purchase price paid by the purchaser to Geokon, Inc. for the unit or units, or equipment directly affected by such breach. Under no circumstances will Geokon reimburse the claimant for loss incurred in removing and/or reinstalling equipment.

Every precaution for accuracy has been taken in the preparation of manuals and/or software, however, Geokon, Inc. neither assumes responsibility for any omissions or errors that may appear nor assumes liability for any damages or losses that result from the use of the products in accordance with the information contained in the manual or software.

TABLE of CONTENTS

1. THEORY OF OPERATION	1
2. INSTALLATION	3
2.1 PRELIMINARY TESTS	3
2.2 SATURATING THE FILTER STONE.....	4
2.3 ESTABLISHING AN INITIAL ZERO READING	4
2.4 CHECKING THE CALIBRATION	4
2.5 INSTALLATION IN BOREHOLES	5
2.5.1 <i>The Drop Weight Method</i>	5
2.5.2 <i>Pneumatic Cutter Method</i>	6
2.5.3 <i>Pull-Pin Method</i>	8
2.6 GROUTING REQUIREMENTS	9
2.7 SPLICING AND JUNCTION BOXES	10
2.8 LIGHTNING PROTECTION	11
3. TAKING READINGS.....	12
3.1 OPERATION OF THE GK-403 READOUT BOX	12
3.2 OPERATION OF THE GK404 READOUT BOX.....	13
4. DATA REDUCTION	14
4.1 PRESSURE CALCULATION	14
4.2 <i>Temperature Correction</i>	16
4.3 <i>Barometric Correction (required only on non-vented transducers)</i>	16
4.3.1 <i>Vented Piezometers</i>	17
4.4 ENVIRONMENTAL FACTORS.....	17
5. TROUBLESHOOTING.....	18
APPENDIX A - SPECIFICATIONS	19
APPENDIX B – STANDARD TEMPERATURE THERMISTOR TEMPERATURE DERIVATION	20
HIGH TEMPERATURE THERMISTOR LINEARIZATION USING STEINHART-HART LOG EQUATION	21
APPENDIX C- NON LINEARITY AND THE USE OF A SECOND ORDER POLYNOMIAL TO IMPROVE THE ACCURACY OF THE CALCULATED PRESSURE.....	22

LIST of FIGURES, TABLES and EQUATIONS

FIGURE 1 MODEL 4500S VIBRATING WIRE PIEZOMETER	1
FIGURE 3. CLOSE UP OF THE 4500MLP DEPLOYED IN THE BOREHOLE.....	2
FIGURE 5 4500MLP TY-WRAPPED FOR DROP WEIGHT METHOD	6
FIGURE 6 PNEUMATIC CUTTER METHOD OF INSTALLATION.....	7
FIGURE 7. PNEUMATIC CUTTER EQUIPMENT	7
FIGURE 8 . MODEL 4500MLP MULTILEVEL PIEZOMETER SHOWN IN CLOSED, PRE-INSTALLED CONFIGURATION (<i>NOTE THAT THE PICTURE SHOWS A SMALL CO₂ CARTRIDGE WHICH IS NO LONGER AVAILABLE.</i>)	8
TABLE 1 SHOWING CEMENT/BENTONITE/WATER RATIOS FOR TWO GROUT MIXES.	10
FIGURE 9 TYPICAL MULTI-PIEZOMETER LIGHTNING PROTECTION	11
FIGURE 10 RECOMMENDED LAB-3 LIGHTNING PROTECTION SCHEME	12
EQUATION 4-1 DIGITS CALCULATION	14
EQUATION 4-2 CONVERT DIGITS TO PRESSURE.....	15
TABLE 2: ENGINEERING UNITS MULTIPLICATION FACTORS.....	15
EQUATION 4-3 TEMPERATURE CORRECTION	16
EQUATION 4-4 BAROMETRIC CORRECTION	16
EQUATION 4-5 CORRECTED PRESSURE CALCULATION.....	17
TABLE A-1 VIBRATING WIRE PIEZOMETER SPECIFICATIONS	19
TABLE B-1 STANDARD TEMPERATURE THERMISTOR RESISTANCE VERSUS TEMPERATURE	20
TABLE B2 HIGH TEMPERATURE. TEMPERATURE V THERMISTOR RESISTANCE	21

1. THEORY OF OPERATION

Geokon Model 4500 Vibrating Wire Piezometers are intended primarily for long-term measurements of fluid and/or pore pressures in standpipes, boreholes, embankments, pipelines and pressure vessels. The Model 4500MLP is designed to permit the easy installation of several piezometers inside a single borehole. **The method eliminates the need for alternating sand and bentonite zones by permitting the entire hole to be backfilled using a bentonite grout tremied in through a grout pipe.**

The basic Model 4500S piezometer, shown in Figure 1, utilizes a sensitive stainless steel diaphragm to which a vibrating wire element is connected. In use, changing pressures on the diaphragm cause it to deflect, and this deflection is measured as a change in tension and frequency of vibration of the vibrating wire element. The square of the vibration frequency is directly proportional to the pressure applied to the diaphragm. Two coils, one with a magnet, another with a pole piece, are located close to the wire. In use, a pulse of varying frequency (swept frequency) is applied to the coils and this causes the wire to vibrate primarily at its resonant frequency. When excitation ends the wire continues to vibrate and a sinusoidal signal, at the resonant frequency, is induced in the coils and transmitted to the readout box where it is conditioned and displayed.




Figure 1 Model 4500S Vibrating Wire Piezometer

For the Model 4500MLP, the filter stone in the figure above is replaced by a tube leading to a much larger, curved, porous filter stone that can be forced against the walls of the borehole by a spring mechanism actuated remotely after the piezometer, in its closed configuration, has been lowered to its desired location. This is shown schematically in figures 2 and 3.

With all the filter stones pressed against the wall of the borehole in this manner the borehole can now be filled completely with a bentonite cement grout without running the risk of getting the filter stone plugged with bentonite or having substantial amounts of highly impervious bentonite interposed between the piezometer diaphragm and the ground water in the surrounding soil.



Figure 2. The 4500MLP System

Figure 3. Close up of the 4500MLP Deployed in the Borehole.

2. INSTALLATION

2.1 Preliminary Tests

Upon receipt of the piezometer the zero reading should be checked and noted (see Sections 3.1 and 3.2 for readout instructions). A thermistor is included inside the body of the piezometer (Figure 1-1) for the measurement of temperature. (See Section 3.3 for instructions).

Calibration data are supplied with each gage and a zero reading, at a specific temperature and absolute barometric pressure, is included. Zero readings at the site should coincide with the factory readings within 20 digits after barometric and temperature corrections are made. (Barometric pressures change with elevation at a rate of about 3.45kPa (½ psi) per 300meters (1,000 ft.)) See Figure 4 for a sample calibration sheet.



 Vibrating Wire Pressure Transducer Calibration								
Model Number: <u>4500S-100</u>			Pressure Range: <u>100 psi</u>					
Serial Number: <u>48056</u>			Mfg. Number: <u>8-3275</u>					
Customer: _____			Temperature: <u>21.1 °C</u>					
Cust. I.D. #: <u>n/a</u>			Barometric Pressure: <u>998.1 mbar</u>					
Job Number: <u>13053</u>			Date: <u>Nov. 7, 1998</u>					
Cal. Std. Control #(s): <u>183, 468</u>			Technician: 					
Pressure (psi)	Reading 1st Cycle	Pressure (psi)	Reading 2nd Cycle	Average Pressure	Average Reading	Change	Linearity (%FS)	Polynomial Fit (%FS)
0	9136	0	9141	0	9139		0.18	-0.04
20	8453	20	8456	20	8455	684	0.03	0.08
40	7772	40	7774	40	7773	682	-0.19	-0.01
60	7085	60	7083	60	7084	689	-0.19	-0.01
80	6392	80	6390	80	6391	693	-0.08	-0.03
100	5694	100	5687	100	5691	701	0.25	0.03
Linear Gage Factor (G): <u>0.029021</u> (psi/digit)			Regression Zero: <u>9145</u>					
Polynomial Gage Factors: A: <u>-1.40E-07</u>			B: <u>-0.026943</u>			C:* <u>257.8826</u>		
Thermal Factor (K): <u>-0.004326</u> (psi/°C)								
Calculated Pressures:			Linear, $P = G(R_0 - R_1) + K(T_1 - T_0) - (S_1 - S_0)**$ Polynomial, $P = AR_1^2 + BR_1 + C + K(T_1 - T_0) - (S_1 - S_0)**$ <i>**Barometric compensation is not required with vented transducers.</i>					
Factory Zero Reading:			GK-401 Pos. B or F(R ₀): <u>9128</u> Temp(T ₀): <u>21.8 °C</u> Baro(S ₀): <u>1001.4mbar</u> Date: <u>Jan. 27, 1997</u>					
<i>*The user is advised to establish zero conditions in the field by recording the reading at a known temperature and barometric pressure.</i>								
Wiring Code: Red and Black: Gage White and Green: Thermistor Bare: Shield								
The above named instrument has been calibrated by comparison with standards traceable to the NIST, in compliance with ANSI Z540-1.								

Figure 4 Sample Calibration Sheet

Care needs to be exercised in choosing the pressure range of the piezometer. During Installation the full pressure of the wet bentonite grout will be felt by the piezometer. Geokon piezometers can withstand over-ranging to 100 percent of the calibrated range without damage and without affecting the calibration or shifting the zero reading. However, at the higher over-range pressures the piezometer may temporarily cease reading until the grout sets up and the pressure returns to normal.

2.2 Saturating the Filter Stone

The filter stone is saturated by first, disconnecting the Swagelok Union at the transducer, and then, by immersing the whole assembly, upside down, in a bucket of water. A vacuum is then applied to the nylon filter tube using the large syringe supplied with the system. This removes the entrapped air from the large filter stone. The transducer itself must be purged of air by injecting water into the Swagelok fitting using the small diameter tube (supplied) attached to the syringe and poked all the way down inside the Swagelok fitting and into the piezometer cavity. Then, while still under water, the nylon tube from the filter stone is reconnected to the transducer. Keep the assembly under water until ready to lower into the borehole.

Caution. – do not allow the piezometer to freeze once it has been filled with water.

2.3 Establishing an Initial Zero Reading

Vibrating Wire Piezometers differ from other types of pressure sensors in that they indicate a reading with no pressure exerted. **It is imperative that an accurate initial zero reading be obtained for each piezometer as this reading will be used for all subsequent data reduction.** Generally, it is obtained by reading the instrument prior to installation (with no pressure applied). The procedure is as follows: With the assembly under water in the bucket allow 5 to 15 minutes for the temperature to stabilize. For this purpose it would be best for the water temperature to be the same as the water temperature in the borehole. Use the thermistor inside the piezometer to measure the water temperature.

When stabilized take a zero reading. Note also the barometric pressure, if possible, or record the time for later referral to local weather station data.

For maximum accuracy record the depth of the piezometer below the water surface at the time of the reading. The piezometer diaphragm is at the same level as the lowest leaf spring.

2.4 Checking the Calibration

The following procedure could be used to verify the calibration factor as supplied on the calibration sheet (Figure 4);

1. Saturate the filter stone and fill the space between it and the diaphragm with water (Section 2.2).
2. Lower the piezometer to the bottom of a water-filled borehole using the cable to measure the actual depth.

3. Allow 15-20 minutes for the piezometer to come to thermal equilibrium. Using a readout box record the reading at that level.
4. Raise the piezometer a known amount. Record the reading. Calculate the factor given the change in pressure and reading. Compare to the calibration sheet value. The two values should agree within $\pm 0.5\%$.

Note: when doing this test be aware that the actual water level inside the borehole might change due to displacement of water by the different lengths of submerged cable. This is especially critical where the cable length is long and the borehole diameter small. Allowing sufficient time for the level to equilibrate may solve this problem. Or keep the borehole full to the top.

2.5 Installation in Boreholes

Borehole sizes are not critical but they should be **at least 100mm (4inch)** in diameter and not more than 30mm larger than the nominal size for which the spring loaded mechanism was designed.

2.5.1 The Drop Weight Method

In steeply inclined boreholes directed downwards the drop-weight method of installation is recommended. For shallow inclinations and upward directed holes, and for other situations where the drop weight method is not desired or possible, the pneumatic cutter method or the pull-pin method can be used, see (Sections 2.5.2 and 2.5.3). Note that the **drop-weight method cannot be used in holes which will not stay open and which require casing to be removed as the piezometers are installed**. This is because in the drop-hammer method the top piezometers are released first.

The 4500MLP sensors are designed to be installed around **flush-coupled 1"schd 80 PVC** grout pipe. Begin by connecting the grout pipe sections together and laying them out along the ground. Mark the desired locations of the piezometers at the calculated depths and then drill a single $7/32$ or $1/4$ inch drill hole diametrically through the pipe.

Each piezometer assembly is held to the grout pipe by means of a single 50lb nylon Ty-
rap, (supplied), that passes diametrically through two holes on opposite sides of the grout pipe. The Ty-
rap also holds the piezometer assembly in its closed position.

The tying sequence is as follows: Pass the Ty-
rap through the grout pipe, then through the spaces between the leaf springs, then around the two platens and then back to itself and pull it tight around the grout pipe. Keep the cables from lower piezometers **inside** the Ty-
rap and leaf springs. The Ty-
rap should pass just **below** the center leaf spring such that the bottom of the platen assemblies will be held tight to the grout pipe. See Figure 5



Figure 5 4500MLP Ty-wrapped for Drop Weight Method

As the grout pipe is assembled and pushed into the borehole the assemblies are added and the electrical cables fed into the hole. When the assembly is completed and the grout tube has reached its final position, a special weight, provided with the equipment, is tied to a length of aircraft cable and is then allowed to fall freely down the inside of the grout pipe. As the weight hits each of the Ty-raps stretching across the pipe the Ty-rap is snapped, allowing the filter stone to be forced against the walls of the borehole.

2.5.2 Pneumatic Cutter Method

The system is designed for installation around **flush-coupled 1" schd 80 PVC** grout pipe, although other grouting arrangements may be used. The assembly is held in its closed position, for installation, by two nylon Ty-raps, (supplied), which are installed through the eyebolts in the platens and through the holes in the cutting tool. Keep the cables from lower piezometers **inside** the Ty-rap and leaf springs. Orient the tool such that it will be above the assembly when pushed into the borehole, and that the grout tube is between the platens, Ty-rap the body of the piezometer to the grout pipe. *See Figure 6.*




Figure 6 Pneumatic Cutter Method of Installation.

Piezometers are installed sequentially from the bottom of the borehole to the mouth. If the **grout pipe** is going to be **removed** from the borehole, the grout pipe is assembled and pushed into the borehole first and then each piezometer assembly must be pushed around the grout pipe, (and any lower piezometer cables), down to the desired elevation. If the grout pipe is to be left in place the piezometers can be taped to the grout pipe, making sure not to put the tape around the outside of the filter stone and spring mechanism.

When the desired elevation is reached the cutting tool is activated by connecting the pneumatic tube from the piezometer to a bottle of CO₂ (obtained locally from any welding supply outlet), The CO₂ bottle should have a pressure regulator which is set to a pressure of at least 2.5MPa, (350 psi), with the shut-off valve closed. (See figure 7). The shut off valve is then opened suddenly allowing the pressure to reach the cutting tool, cutting the ty-wraps and releasing the spring-loaded platens against the borehole walls.




Figure 7. Pneumatic Cutter Equipment

If installed in drill casing, the sensor is lowered to the proposed elevation and the casing is pulled just above this elevation before the assembly is released. The cutting tool is then removed from the drill hole and the next assembly prepared for installation. When lowering the next and subsequent piezometers down the hole, feed the cables from the lower piezometers through the middle of the assembled piezometer rather than around the outside. (This will prevent the cables from interfering with the filter and preventing its close contact with the borehole wall).

When all the assemblies are installed the hole can be grouted from the bottom up using a bentonite cement grout.




Figure 8 Model 4500MLP Multilevel Piezometer shown in closed, pre-installed configuration (Note that the picture shows a small CO₂ cartridge which is no longer available.)

2.5.3 Pull-Pin Method

In this method the piezometer assembly is held in its closed position by means of a pull-pin, which, after the filter stone and the platen are squeezed together, passes through both sets of three eyebolts mounted on the filter stone and the platen.

If the **grout pipe** is going to be **removed** from the borehole, the piezometer assembly must be pushed around the grout pipe down to the desired elevation using a second push pipe, which can be another length of the grout tube. While holding the piezometer in position by the push-in pipe, the pull-pin cable should be pulled gently until all the slack is taken out, and then pulled with a sudden strong jerk, which will release the platens without changing the position of the piezometer relative to the borehole. **A bit of practice pulling the pins before the actual installation will give some "feeling" and confidence as to how the system works.**

Piezometers should be installed sequentially from the bottom(top) of the borehole to the mouth.

If the **grout pipe** is going to be **left in** the borehole the piezometer assemblies can be attached to it in a manner that does not restrict the movement of the platens. The grout pipe can be assembled, length-by-length, and the piezometer assemblies, each with its own pull-pin, can be attached to it by taping the electrical cable to the grout tube close to the piezometer. The grout pipe and piezometer assemblies can then be pushed down the hole as a unit. When the final position is reached the pull-pins can then be pulled, activating the platens.

If installed in drill casing, the sensor is lowered to the proposed elevation and the casing is pulled just above this elevation before the assembly is released. The tool is then removed from the drillhole and the next assembly prepared for installation. When lowering or pushing the next and subsequent piezometers down the hole, feed the cables from the lower piezometers through the middle of the assembled piezometer rather than around the outside. This will prevent the cables from interfering with the filter and preventing close contact with the borehole wall.

When all the assemblies are installed the hole can be grouted from the bottom up using a bentonite cement grout. The grout pipe can be either removed from the hole or left in place.

2.6 Grouting requirements

For more details on this topic, refer to “Piezometers in Fully Grouted Boreholes” by Mikkelsen and Green, FMGM proceedings Oslo 2003. A copy is available from Geokon.

The general rule for grouting multi level piezometers is to mimic the strength of the surrounding soil. The emphasis should be on controlling the water-cement ratio. This is accomplished by **mixing the cement with the water first**.

The most effective way of mixing is in a 50 to 200 gallon barrel or tub using the drill-rig pump to circulate the mix. Any kind of bentonite powder used to make drilling mud, combined with Type 1 or 2 Portland cement can be used. The exact amount of bentonite added will vary somewhat. The table below shows 2 possible mixes for strengths of 50 psi and 4 psi.

Add the measured amount of clean water to the barrel then gradually add the cement in the correct weight ratio. Next add the bentonite powder, slowly, so clumps do not form. Keep adding bentonite until the watery mix turns to an oily/slimy consistency. Let the grout thicken for another five to ten minutes. Add more bentonite as required until it is a smooth thick cream like pancake batter. It is now as heavy as it is feasible to pump. When pumping grout, unless the tremie-pipe is to be left in place, withdraw the tremie-pipe after each batch, by an amount corresponding to the grout level in the borehole.

Application	Grout for Medium to Hard Soils		Grout for Soft Soils	
	Weight	Ratio by Weight	Weight	Ratio by Weight
Water	30 gallons	2.5	75 gallons	6.6

Portland Cement	94 lbs (1 sack)	1	94 lbs (1 sack)	1
Bentonite	25 lbs (as required)	0.3	39 lbs (as required)	0.4
Notes	The 28 day compressive strength of this mix is about 50 psi, similar to very stiff to hard clay. The modulus is about 10,000 psi		The 28 day strength of this mix is about 4psi, similar to very soft clay.	

Table 1 showing Cement/bentonite/water ratios for two grout mixes.

2.7 Splicing and Junction Boxes

Because the vibrating wire output signal is a frequency rather than current or voltage, variations in cable resistance have little effect on gage readings and, therefore, splicing of cables has no effect either and, in some cases, may be beneficial. For example, if multiple piezometers are installed in a borehole, and the distance from the borehole to the terminal box or datalogger is great, a splice (or junction box, see Figure 6) could be made to connect the individual cables to a single multi-conductor cable. This multi-conductor cable would then be run to the readout station. For such installations it is recommended that the piezometer be supplied with enough cable to reach the installation depth plus extra cable to pass through drilling equipment (rods, casing, etc.).

The cable used for making splices should be a high quality twisted pair type with 100% shielding (with integral shield drain wire). When splicing, it is very important that the shield drain wires be spliced together! Splice kits recommended by Geokon incorporate casts placed around the splice then filled with epoxy to waterproof the connections. When properly made, this type of splice is equal or superior to the cable itself in strength and electrical properties. Contact Geokon for splicing materials and additional cable splicing instructions.

Junction boxes and terminal boxes are available from Geokon for all types of applications. In addition, portable readout equipment and datalogging hardware are available. See Figure 9. Contact Geokon for specific application information.




Figure 9 Typical Multi-Piezometer Lightning Protection

2.8 Lightning Protection

In exposed locations it is vital that the piezometer be protected against lightning strikes.

A tripolar plasma surge arrestor (see Figure 1) is built into the body of the piezometer and protects against voltage spikes across the input leads. Following are additional lightning protection measures available;

1. If the instruments will be read manually with a portable readout (no terminal box) a simple way to help protect against lightning damage is to connect the cable leads to a good earth ground when not in use. This will help shunt transients induced in the cable to ground thereby protecting the instrument.
2. Terminal boxes available from Geokon can be ordered with lightning protection built in. There are two levels of protection;
 - The terminal board used to make the gage connections has provision for installation of plasma surge arrestors (similar to the device inside the piezometer).
 - Lightning Arrestor Boards (LAB-3) can be incorporated into the terminal box. These units utilize surge arrestors and transzorb to further protect the piezometer.

In the above cases the terminal box would be connected to an earth ground.

- Improved protection using the LAB-3 can be had by placing the board in line with the cable as close as possible to the installed piezometer (see Figure 10). This is the recommended method of lightning protection.




Figure 10 Recommended Lab-3 Lightning Protection Scheme

3. TAKING READINGS

3.1 Operation of the GK-401 Readout Box

Connect the Readout using the flying leads or in the case of a terminal station, with a connector. The red and black clips are for the vibrating wire gage, the green lead for the shield drain wire. The GK-401 cannot read the thermistor (see Section 3.4).

- Turn the display selector to position "B" (or "F"). Readout is in digits (Equation 4-1).
- Turn the unit on and a reading will appear in the front display window. The last digit may change one or two digits while reading. Record the value displayed. If zeros are displayed or the reading is unstable see section 5 for troubleshooting suggestions.
- The unit will automatically turn itself off after approximately 4 minutes to conserve power.

3.1 Operation of the GK-403 Readout Box

The GK-403 can store gage readings and also apply calibration factors to convert readings to engineering units. Consult the GK-403 Instruction Manual for additional information on Mode "G" of the Readout. The following instructions will explain taking gage measurements using Modes "B" and "F" (similar to the GK-401 switch positions "B" and "F").

Connect the Readout using the flying leads or in the case of a terminal station, with a connector. The red and black clips are for the vibrating wire gage, the white and green leads are for the thermistor and the blue for the shield drain wire.

1. Turn the display selector to position "B" (or "F"). Readout is in digits (Equation 4-1).
2. Turn the unit on and a reading will appear in the front display window. The last digit may change one or two digits while reading. Press the "Store" button to record the value displayed. If the no reading displays or the reading is unstable see section 5 for troubleshooting suggestions. The thermistor will be read and output directly in degrees centigrade.
3. The unit will automatically turn itself off after approximately 2 minutes to conserve power.

3.2 Operation of the GK404 Readout Box

The GK404 is a palm sized readout box which displays the Vibrating wire value and the temperature in degrees centigrade.

The GK-404 Vibrating Wire Readout arrives with a patch cord for connecting to the vibrating wire gages. One end will consist of a 5-pin plug for connecting to the respective socket on the bottom of the GK-404 enclosure. The other end will consist of 5 leads terminated with alligator clips. Note the colors of the alligator clips are red, black, green, white and blue. The colors represent the positive vibrating wire gage lead (red), negative vibrating wire gage lead (black), positive thermistor lead (green), negative thermistor lead (white) and transducer cable drain wire (blue). The clips should be connected to their respectively colored leads from the vibrating wire gage cable.

Use the **POS** (Position) button to select position **B** and the **MODE** button to select **Dg** (digits).

Other functions can be selected as described in the GK404 Manual.

The GK-404 will continue to take measurements and display the readings until the **OFF** button is pushed, or if enabled, when the automatic Power-Off timer shuts the GK-404 off.

The GK-404 continuously monitors the status of the (2) 1.5V AA cells, and when their combined voltage drops to 2V, the message **Batteries Low** is displayed on the screen. A fresh set of 1.5V AA batteries should be installed at this point

3.4 Measuring Temperatures

Each vibrating wire piezometer is equipped with a thermistor for reading temperature. The thermistor gives a varying resistance output as the temperature changes. Usually the

white and green leads are connected to the internal thermistor. High temperature versions use a different thermistor than the standard versions.

The GK-403 and GK-404 readout boxes when used with the **standard** temperature thermistor will display the temperature in °C automatically. It will **not** do this with high temperature thermistors.

The GK 401 readout box will not read temperatures directly, instead an ohmmeter must be used:

1. Connect the ohmmeter to the green and white thermistor leads coming from the piezometer. (Since the resistance changes with temperature are so large, the effect of cable resistance is usually insignificant. For long cables a correction can be applied – equal to 22 ohms per thousand feet.)
2. For standard temperature models, look up the temperature for the measured resistance in Table B-1. Page 17. Alternatively the temperature could be calculated using Equation B-1. For high temperature models use Table B2 or the equation B2 given on page 18.

4. DATA REDUCTION

4.1 Pressure Calculation

The digits displayed by the Geokon Models GK-401, GK-403 or GK404 Readout Boxes on channel B are based on the equation

$$\text{Digits} = \left(\frac{1}{\text{Period}} \right)^2 \times 10^{-3} \quad \text{or} \quad \text{Digits} = \frac{\text{Hz}^2}{1000}$$

Equation 4-1 Digits Calculation

For example, a piezometer reading 8000 digits corresponds to a period of 354µs and a frequency of 2828 Hz. Note that in the above equation, the period is in seconds: the readout boxes display microseconds.

Since digits are directly proportional to the applied pressure,

$$\text{Pressure} = (\text{Initial Reading} - \text{Current Reading}) \times \text{Calibration Factor}$$

or

$$P = (R_0 - R_1) \times G$$

Equation 4-2 Convert Digits to Pressure

Since the linearity of most sensors is within 0.2% FS the errors associated with non-linearity are of minor consequence. However, for those situations requiring the highest accuracy it may be desirable to use a second order polynomial to get a better fit of the data points. The use of a second order polynomial is explained in Appendix C. Page 19.

The calibration sheet, a typical example of which is shown in figure 4 on page 5, shows the data from which the linear gage factor and the second order polynomial coefficients are derived. Columns on the right show the size of the error incurred by assuming a linear coefficient and the improvement, which can be expected by going to a second order polynomial. In many cases the difference is minor. The calibration sheet gives the pressure in specific engineering units. These can be converted to other engineering units using the multiplication factors shown in the table below.

From → To ↓	psi	"H ₂ O	'H ₂ O	mm H ₂ O	m H ₂ O	"HG	mm HG	atm	mbar	bar	kPa	MPa
psi	1	.036127	.43275	.0014223	1.4223	.49116	.019337	14.696	.014503	14.5039	.14503	145.03
"H ₂ O	27.730	1	12	.039372	39.372	13.596	.53525	406.78	.40147	401.47	4.0147	4016.1
'H ₂ O	2.3108	.08333	1	.003281	3.281	1.133	.044604	33.8983	.033456	33.4558	.3346	334.6
mm H ₂ O	704.32	25.399	304.788	1	1000	345.32	13.595	10332	10.197	10197	101.97	101970
m H ₂ O	.70432	.025399	.304788	.001	1	.34532	.013595	10.332	.010197	10.197	.10197	101.97
"HG	2.036	.073552	.882624	.0028959	2.8959	1	.03937	29.920	.029529	29.529	.2953	295.3
mm HG	51.706	1.8683	22.4196	.073558	73.558	25.4	1	760	.75008	750.08	7.5008	7500.8
atm	.06805	.0024583	.0294996	.0000968	.0968	.03342	.0013158	1	.0009869	.98692	.009869	9.869
mbar	68.947	2.4908	29.8896	.098068	98.068	33.863	1.3332	1013.2	1	1000	10	10000
bar	.068947	.0024908	.0298896	.0000981	.098068	.033863	.001333	1.0132	.001	1	.01	10
kPa	6.8947	.24908	2.98896	.0098068	9.8068	3.3863	.13332	101.320	.1	100	1	1000
MPa	.006895	.000249	.002988	.00000981	.009807	.003386	.000133	.101320	.0001	.1	.001	1

Table 2: Engineering Units Multiplication Factors

Note: Due to changes in specific gravity with temperature the factors for mercury and water in the above table are approximations!

4.2 Temperature Correction

Careful selection of materials is made in constructing the vibrating wire piezometer to minimize thermal effects, however, most units still have a slight temperature coefficient. Consult the supplied calibration sheet to obtain the coefficient for a given piezometer. Since piezometers are normally installed in a tranquil and constant temperature environment, corrections are not normally required. If however, that is not the case for a selected installation, corrections can be made using the internal thermistor (see Figure 1) for temperature measurement. See Section 3.3 for instructions regarding obtaining the piezometer temperature.

Temperature correction equation is as follows;

$$\text{Temperature Correction} = (\text{Current Temperature} - \text{Initial Temperature}) \times \text{Thermal Factor}$$

or

$$P_T = (T_1 - T_0) \times K$$

Equation 4-3 Temperature Correction

The calculated correction would then be **added** to the Pressure calculated using Equation 4-2. If the engineering units were converted remember to apply the same conversion to the calculated temperature correction!

For example, assume the initial temperature was 22° C, the current temperature is 15° C, and the thermal coefficient is –0.004326 PSI per °C rise (Figure 4). The temperature correction is +0.03 PSI

4.3 Barometric Correction (required only on non-vented transducers)

Since the standard piezometer is hermetically sealed and unvented, it responds to changes in atmospheric pressure. That being the case, corrections may be necessary, particularly for the sensitive, low pressure models. For example, a barometric pressure change from 29 to 31 inches of mercury would result in ≈1 PSI of error (or ≈2.3 feet if monitoring water level in a well!). Thus it is advisable to read and record the barometric pressure every time the piezometer is read. A separate pressure transducer (piezometer), kept out of the water, may be used for this purpose.

Barometric correction equation is as follows;

$$\text{Barometric Correction} = (\text{Current Barometer} - \text{Initial Barometer}) \times \text{Conversion Factor}$$

or

$$P_B = (S_1 - S_0) \times F$$

Equation 4-4 Barometric Correction

Since barometric pressure is usually recorded in inches of mercury a Conversion Factor is necessary to convert to PSI. The Conversion Factor for inches of mercury to PSI is .491. Table 2 lists other common Conversion Factors.

The calculated barometric correction is **subtracted** from the Pressure calculated using Equation 4-2. If the engineering units were converted remember to apply the same conversion to the calculated barometric correction!

The user should be cautioned that this correction scheme assumes ideal conditions. In reality, conditions are not always ideal. For example, if the well is sealed, barometric effects at the piezometer level may be minimal or attenuated from the actual changes at the surface. Thus errors may result when applying a correction, which is not required. We recommend, in these cases, to independently record barometric pressure changes and correlate these with observed pressure changes to arrive at a correction factor.

An alternative to making barometric correction is to use piezometers that are vented to the atmosphere. Note section 4.3.1.

Equation 4-5 describes the pressure calculation with temperature and barometric correction applied.

$$P_{\text{corrected}} = ((R_0 - R_1) \times G) + ((T_1 - T_0) \times K) - ((S_1 - S_0) \times F)$$

Equation 4-5 Corrected Pressure Calculation

4.3.1 Vented Piezometers

Vented piezometers are designed to eliminate barometric effects. The space inside the transducer is not hermetically sealed and evacuated (see Figure 1), but is connected via a tube (integral with the cable) to the atmosphere. A chamber, containing desiccant capsules, is attached to the end of the tube to prevent moisture from entered the transducer cavity. Vented piezometers require more maintenance than non-vented types, and there is always a danger that water can find its way into the inside of the transducer and ruin it.

As supplied, the outer end of the desiccant chamber is closed by means of a seal screw to keep the desiccant fresh during storage and transportation. **THE SEAL SCREW MUST BE REMOVED BEFORE THE PIEZOMETER IS PUT INTO SERVICE!** The desiccant capsules are blue when fresh. They will gradually turn pink as they absorb moisture. When they have turned light pink in color they should be replaced. Contact Geokon for replacement capsules.

4.4 Environmental Factors

Since the purpose of the piezometer installation is to monitor site conditions, factors which may affect these conditions should always be observed and recorded. Seemingly minor effects may have a real influence on the behavior of the structure being monitored and may give an early indication of potential problems. Some of the factors include, but are not limited to; blasting, rainfall, tidal levels, excavation and fill levels and sequences, traffic, temperature and barometric changes (and other weather conditions), changes in personnel, nearby construction activities, seasonal changes, etc.

5. TROUBLESHOOTING

Maintenance and troubleshooting of vibrating wire piezometers is confined to periodic checks of cable connections and maintenance of terminals. The transducers themselves are sealed and not user serviceable. Following are typical problems and suggested remedial action.

- **Piezometer fails to give a reading**

1. Check the resistance of the coils by connecting an ohmmeter across the gage terminals. Nominal resistance is 180Ω ($\pm 5\%$), plus cable resistance at approximately 15Ω per 1000' of 22 AWG wire. If the resistance is very high or infinite the cable is probably broken or cut. If the resistance is very low the gage conductors may be shorted. If a cut or a short is located in the cable, splice according to instructions in Section 2.7.
2. Check the readout with another gage.
3. The Piezometer may have been over-ranged or shocked. Inspect the diaphragm and housing for damage. Contact the factory.

- **Piezometer reading unstable**

1. Connect the shield drain wire to the readout using the green (GK-401) or the blue (GK-403) clip.
2. Isolate the readout from the ground by placing it on a piece of wood or similar non-conductive material.
3. Check for sources of nearby noise such as motors, generators, antennas or electrical cables. Move the piezometer cables if possible. Contact the factory for filtering and shielding equipment available.
4. The Piezometer may have been damaged by over-ranging or shock.
5. The body of the Piezometer may be shorted to the shield. Check the resistance between the shield drain wire and the Piezometer housing.

- **Thermistor resistance is too high**

1. Likely there is an open circuit. Check all connections, terminals and plugs. If a cut is located in the cable, splice according to instructions in Section 2.7.

- **Thermistor resistance is too low**

1. Likely there is a short. Check all connections, terminals and plugs. If a short is located in the cable, splice according to instructions in Section 2.7.
2. Water may have penetrated the interior of the piezometer. There is no remedial action.

APPENDIX A - SPECIFICATIONS

Model	4500S	4500AL ¹	4500B	4500C	4580 ²
Available Ranges (psi)	0-50 0-100 0-150 0-250 0-500 0-750 0-1000 0-1500 0-3000 0-5000 0-10000 0-15000	0-5 0-10 0-25	0-50 0-100 0-250	0-50 0-100 0-250	0-1 0-5
Resolution	0.025% FS	0.025% FS	0.025% FS	0.05% FS	0.01% FS
Linearity	0.5% FS ³	0.5% FS ³	0.5% FS ³	0.5% FS ³	0.5% FS ³
Accuracy	0.1% FS ⁴	0.1% FS ⁴	0.1% FS ⁴	0.1% FS ⁴	0.1% FS
Over-Range	2 × FS	2 × FS	2 × FS	2 × FS	2 × FS
Thermal Coefficient	<0.025% FS/ °C	<0.05% FS/ °C	<0.025% FS/ °C	<0.05% FS/ °C	<0.025% FS/ °C
OD	.75" 19.05 mm	1" 25.40 mm	.687" 17.45 mm	.437" 11.10 mm	1.5" 38.10 mm
Length	5.25" 133.35 mm	5.25" 133.35 mm	5.25" 133.35 mm	6.5" 165.10 mm	6.5" 165.10 mm
Frequency Range Hz	1400-3500	1400-3500	1400-3500	1400-3500	1400-3500

Table A-1 Vibrating Wire Piezometer Specifications

Notes:

¹ Accuracy of test apparatus: 0.05%² Other ranges available upon request.³ 0.1% FS linearity available upon request.⁴ Derived using 2nd order polynomial.

**APPENDIX B – STANDARD TEMPERATURE THERMISTOR
TEMPERATURE DERIVATION**

Thermistor Type: YSI 44005, Dale #1C3001-B3, Alpha #13A3001-B3

Resistance to Temperature Equation B1:

$$T = \frac{1}{A + B(\ln R) + C(\ln R)^3} - 273.2$$

Where; T = Temperature in °C.

LnR = Natural Log of Thermistor Resistance

A = 1.4051×10^{-3} (coefficients calculated over the -50 to +150° C. span)

B = 2.369×10^{-4}

C = 1.019×10^{-7}

Ohms	Temp	Ohms	Temp	Ohms	Temp	Ohms	Temp	Ohms	Temp
201.1K	-50	16.60K	-10	2417	+30	525.4	+70	153.2	+110
187.3K	-49	15.72K	-9	2317	31	507.8	71	149.0	111
174.5K	-48	14.90K	-8	2221	32	490.9	72	145.0	112
162.7K	-47	14.12K	-7	2130	33	474.7	73	141.1	113
151.7K	-46	13.39K	-6	2042	34	459.0	74	137.2	114
141.6K	-45	12.70K	-5	1959	35	444.0	75	133.6	115
132.2K	-44	12.05K	-4	1880	36	429.5	76	130.0	116
123.5K	-43	11.44K	-3	1805	37	415.6	77	126.5	117
115.4K	-42	10.86K	-2	1733	38	402.2	78	123.2	118
107.9K	-41	10.31K	-1	1664	39	389.3	79	119.9	119
101.0K	-40	9796	0	1598	40	376.9	80	116.8	120
94.48K	-39	9310	+1	1535	41	364.9	81	113.8	121
88.46K	-38	8851	2	1475	42	353.4	82	110.8	122
82.87K	-37	8417	3	1418	43	342.2	83	107.9	123
77.66K	-36	8006	4	1363	44	331.5	84	105.2	124
72.81K	-35	7618	5	1310	45	321.2	85	102.5	125
68.30K	-34	7252	6	1260	46	311.3	86	99.9	126
64.09K	-33	6905	7	1212	47	301.7	87	97.3	127
60.17K	-32	6576	8	1167	48	292.4	88	94.9	128
56.51K	-31	6265	9	1123	49	283.5	89	92.5	129
53.10K	-30	5971	10	1081	50	274.9	90	90.2	130
49.91K	-29	5692	11	1040	51	266.6	91	87.9	131
46.94K	-28	5427	12	1002	52	258.6	92	85.7	132
44.16K	-27	5177	13	965.0	53	250.9	93	83.6	133
41.56K	-26	4939	14	929.6	54	243.4	94	81.6	134
39.13K	-25	4714	15	895.8	55	236.2	95	79.6	135
36.86K	-24	4500	16	863.3	56	229.3	96	77.6	136
34.73K	-23	4297	17	832.2	57	222.6	97	75.8	137
32.74K	-22	4105	18	802.3	58	216.1	98	73.9	138
30.87K	-21	3922	19	773.7	59	209.8	99	72.2	139
29.13K	-20	3748	20	746.3	60	203.8	100	70.4	140
27.49K	-19	3583	21	719.9	61	197.9	101	68.8	141
25.95K	-18	3426	22	694.7	62	192.2	102	67.1	142
24.51K	-17	3277	23	670.4	63	186.8	103	65.5	143
23.16K	-16	3135	24	647.1	64	181.5	104	64.0	144
21.89K	-15	3000	25	624.7	65	176.4	105	62.5	145
20.70K	-14	2872	26	603.3	66	171.4	106	61.1	146
19.58K	-13	2750	27	582.6	67	166.7	107	59.6	147
18.52K	-12	2633	28	562.8	68	162.0	108	58.3	148
17.53K	-11	2523	29	543.7	69	157.6	109	56.8	149
								55.6	150

**Table B-1 STANDARD TEMPERATURE Thermistor Resistance versus
Temperature**

High Temperature Thermistor Linearization using SteinHart-Hart Log Equation

Thermistor Type: Thermometrics BR55KA822J

Basic Equation B2:
$$T = \frac{1}{A + B(\text{LnR}) + C(\text{LnR})^3} - 273.2$$

Where: T = Temperature in °C.

LnR = Natural Log of Thermistor Resistance

$$A = 1.02569 \times 10^{-3}$$

$$B = 2.478265 \times 10^{-4}$$

$$C = 1.289498 \times 10^{-7}$$

Note: Coefficients calculated over -30° to +260° C. span.

Table B2

Temp	R (ohms)	LnR	LnR ³	Calculate d Temp	Diff	FS Error	Temp	R (ohms)	LnR	LnR ³	Calculate d Temp	Diff	FS Error
-30	113898	11.643	1578.342	-30.17	0.17	0.06	120	407.62	6.010	217.118	120.00	0.00	0.00
-25	86182	11.364	1467.637	-25.14	0.14	0.05	125	360.8	5.888	204.162	125.00	0.00	0.00
-20	65805	11.094	1365.581	-20.12	0.12	0.04	130	320.21	5.769	191.998	130.00	0.00	0.00
-15	50684.2	10.833	1271.425	-15.10	0.10	0.03	135	284.95	5.652	180.584	135.00	0.00	0.00
-10	39360	10.581	1184.457	-10.08	0.08	0.03	140	254.2	5.538	169.859	140.01	-0.01	0.00
-5	30807.4	10.336	1104.068	-5.07	0.07	0.02	145	227.3	5.426	159.773	145.02	-0.02	-0.01
0	24288.4	10.098	1029.614	-0.05	0.05	0.02	150	203.77	5.317	150.314	150.03	-0.03	-0.01
5	19294.6	9.868	960.798	4.96	0.04	0.01	155	183.11	5.210	141.428	155.04	-0.04	-0.01
10	15424.2	9.644	896.871	9.98	0.02	0.01	160	164.9	5.105	133.068	160.06	-0.06	-0.02
15	12423	9.427	837.843	14.98	0.02	0.01	165	148.83	5.003	125.210	165.08	-0.08	-0.03
20	10061.4	9.216	782.875	19.99	0.01	0.00	170	134.64	4.903	117.837	170.09	-0.09	-0.03
25	8200	9.012	731.893	25.00	0.00	0.00	175	122.1	4.805	110.927	175.08	-0.08	-0.03
30	6721.54	8.813	684.514	30.01	-0.01	0.00	180	110.95	4.709	104.426	180.07	-0.07	-0.02
35	5540.74	8.620	640.478	35.01	-0.01	0.00	185	100.94	4.615	98.261	185.10	-0.10	-0.04
40	4592	8.432	599.519	40.02	-0.02	-0.01	190	92.086	4.523	92.512	190.09	-0.09	-0.03
45	3825.3	8.249	561.392	45.02	-0.02	-0.01	195	84.214	4.433	87.136	195.05	-0.05	-0.02
50	3202.92	8.072	525.913	50.01	-0.01	-0.01	200	77.088	4.345	82.026	200.05	-0.05	-0.02
55	2693.7	7.899	492.790	55.02	-0.02	-0.01	205	70.717	4.259	77.237	205.02	-0.02	-0.01
60	2276.32	7.730	461.946	60.02	-0.02	-0.01	210	64.985	4.174	72.729	210.00	0.00	0.00
65	1931.92	7.566	433.157	65.02	-0.02	-0.01	215	59.819	4.091	68.484	214.97	0.03	0.01
70	1646.56	7.406	406.283	70.02	-0.02	-0.01	220	55.161	4.010	64.494	219.93	0.07	0.02
75	1409.58	7.251	381.243	75.01	-0.01	0.00	225	50.955	3.931	60.742	224.88	0.12	0.04
80	1211.14	7.099	357.808	80.00	0.00	0.00	230	47.142	3.853	57.207	229.82	0.18	0.06
85	1044.68	6.951	335.915	85.00	0.00	0.00	235	43.673	3.777	53.870	234.77	0.23	0.08
90	903.64	6.806	315.325	90.02	-0.02	-0.01	240	40.533	3.702	50.740	239.69	0.31	0.11
95	785.15	6.666	296.191	95.01	-0.01	0.00	245	37.671	3.629	47.788	244.62	0.38	0.13
100	684.37	6.528	278.253	100.00	0.00	0.00	250	35.055	3.557	45.001	249.54	0.46	0.16
105	598.44	6.394	261.447	105.00	0.00	0.00	255	32.677	3.487	42.387	254.44	0.56	0.19
110	524.96	6.263	245.705	110.00	0.00	0.00	260	30.496	3.418	39.917	259.34	0.66	0.23
115	461.91	6.135	230.952	115.00	0.00	0.00							

Table B2 High Temperature. Temperature v Thermistor Resistance

APPENDIX C- NON LINEARITY AND THE USE OF A SECOND ORDER POLYNOMIAL TO IMPROVE THE ACCURACY OF THE CALCULATED PRESSURE

Most vibrating wire pressure transducers are sufficiently linear, ($\pm 0.2\%$ FS), that use of the linear calibration factor satisfies normal requirements. However, it should be noted that the accuracy of the calibration data points, which is dictated by the accuracy of the calibration apparatus, is always $\pm 0.1\%$ FS.

This level of accuracy can be recaptured even where the transducer is non-linear, by the use of a second order polynomial expression, which gives a better fit to the data than does a straight line.

The polynomial expression has the form:

$$\text{Pressure} = AR^2 + BR + C$$

where R is the reading (digits channel B) and A,B,C, are coefficients. The figure on page 24 shows a calibration sheet of a transducer, which has a comparatively high non-linearity. The figure under the "Linearity (%FS)" column is

$$\frac{\text{Calculated pressure} - \text{True pressure}}{\text{Full-scale Pressure}} \times 100\% = \frac{G(R_0 - R_1) - P}{F.S.} \times 100\%$$

Note: The linearity is calculated using the regression zero for R_0

For example when $P = 40$ psi, $G(R_0 - R_1) = 0.029021(9145 - 7773)$, gives a calculated pressure of 39.817 psi. The error is 0.183 psi equal to 5 inches of water.

Whereas the polynomial expression gives a calculated pressure of $A(7773)^2 + B(7773) + C = 39.996$ psi and the actual error is only 0.004 psi or 0.1 inch of water.

Note. If the polynomial equation is used it is important that the value of C, in the polynomial equation, be taken in the field, following the procedures described in section 2.1.1. The field value of C is calculated by inserting the initial zero reading into the polynomial equation with the pressure, P, set to zero.

It should be noted that where changes of water levels are being monitored it makes little difference whether the linear coefficient or the polynomial expression is used.