


# Profile of inclinometer casing in plane perpendicular to the M25 Motorway (positive values lie closer to the motorway)



© Geotechnical Observations Limited 2000-2004. All rights reserved.

**Figure 2:** Location of in-place sensors